ERT Document PE317-600



DRIFT-PLATTEVILLE AQUIFER
NORTHERN AREA REMEDIAL INVESTIGATION PLAN
FOR THE REILLY TAR & CHEMICAL CORPORATION
N.P.L. SITE, ST. LOUIS PARK, MINNESOTA

November 3, 1986

Prepared for:

The City of St. Louis Park
St. Louis Park, Minnesota 55416

ERT - A RESOURCE ENGINEERING COMPANY 5871 Cedar Lake Road, St. Louis Park, Minnesota 55416

CONTENTS

Section A Site Management Plan

Section B Quality Assurance Project Plan

Section C Health & Safety Plan

Section D Community Relations Plan

SECTION A

SITE MANAGEMENT PLAN

•	
	*

Background

حتت

Section 9.3 of the Remedial Action Plan (RAP) outlines the requirements for a Remedial Investigation (RI) for the Northern Area of the Drift-Platteville Aquifer. The Northern Area is bounded by West 32nd Street to the north, Alabama Avenue to the east, Highway 7 to the south, and Louisiana Avenue to the west (Figure 1). The RAP requires six new monitoring wells and the collection of water quality samples from the new wells and existing wells to determine the nature and extent of contamination in the Northern Area of the Drift-Platteville Aquifer. This Remedial Investigation Plan specifies the location and design of the six new monitoring wells. The Drift-Platteville Aquifer monitoring wells will be sampled twice for analysis of PAH and phenolic compounds (including water level measurements) and a report summarizing the results of the Remedial Investigation will be prepared.

Pollen US EAR DES /FS juidances

NON-RESPONSIVE

	•
	•
	Á
	Ě
	—
	· ·
	•
	£
o .	•
	T
	,
	1 ,
•	_
	~
	•
	!
	T.
	À
	•

Well Locations

Figure 1 shows the proposed locations for the six new monitoring wells and the locations of existing Drift-Platteville Aquifer monitoring wells that will be monitored concurrently with this investigation. The six new monitoring wells will consist of three wells completed in the Drift Aquifer and three wells completed in the Platteville Aquifer. Figure 1 indicates one Drift Aquifer monitoring well and one Platteville Aquifer monitoring well at each of three locations. These three locations, combined with the location of existing monitoring wells W131 and W136, provide a good aerial coverage of the northern area of the Drift-Platteville Aquifer.

The six new monitoring wells and well PB140 will be designated using the USGS well numbering system upon concurrence of all Project Leaders. The wells will be located in St. Louis Park, and the City will aquire necessary access agreements in those instances where others own the site where the monitoring wells will be located.

Well Design and Installation

The design for the six new Drift-Platteville Aquifer monitoring wells is consistent with the design for existing monitoring wells in this aquifer. A licensed well driller will be contracted to install the monitoring wells in accordance with the Minnesota Department of Health Water Well Construction Code. The wells will be completed within 60 days of receiving approval of this plan.

sparty

Figure 2 shows the well design that will be used for Drift and Platteville Aquifer monitoring wells. Four-inch diameter steel casing will be used for each monitoring well, with open-hole completion through the Platteville Aquifer. Screens used for the Drift Aquifer monitoring wells will be of stainless steel construction, and will be 5 to 10 feet long based upon observations of the City's field representative. At each location the Platteville Aquifer monitoring well will be drilled first. The geologic information gained during that installation will be used to guide the placement of the screened interval for the adjacent Drift Aquifer monitoring well. The Drift Aquifer monitoring wells will be screened in a coarse sandy zone of the Middle Drift Aquifer. Well heads will consist of the 4-inch casing extending approximately two feet above the ground surface. A hinged, lockable, steel cover will be used to cap the 4-inch casing. The casing will be painted and marked with the well's project number, and regular inspections will be made to minimize vandalism.

- u/ find offered bythe agrans.





Figure 2. Conceptual Design of Monitoring Wells



The licensed well contractor will use direct rotary drilling techniques to advance 8-inch diameter boreholes. For Platteville Aquifer monitoring wells, the 4-inch casing will be set within the upper five feet of the Platteville Formation, and will be grouted from the inside out. Additional grout will be placed via tremie pipe, if required. A 4-inch diameter open hole will then be drilled through the Platteville Aquifer. For Drift Aquifer wells, 4-inch diameter, stainless steel screens will be welded onto the bottom of the casing and inserted into the completed borehole. A filter pack of graded coarse sand will be installed around the screen to two feet above the screen. A two-foot thick bentonite seal will then be added and the remainder of the hole will be grouted and sealed at the surface with a cement collar. All grout and other well construction materials will conform with the requirements of the Minnesota Water Well Construction Code and will be left-to-the discretion of the well contractor. Upon completion, the wells will be developed using appropriate industry methods as directed by the City's field representative. Disinfectants will not be used, as they may interfere with subsequent water quality analyses.

The drilling sites will be kept neat and clean at all times. Drilling fluids, cuttings, and other debris will be containerized and hauled off-site-by-the-well-contractor-for-disposal-as-clean.fill.

Drilling tools and equipment will be cleaned between wells. A record containing documentation of these procedures and field notes, field measurements, well logs, etc. will be maintained.

Sampling and Analysis

Within 30 days of completing the new monitoring well installations, ground-water samples will be collected for PAH and phenolies analyses. A second round of monitoring will be conducted within six months of the first monitoring round. All sampling and analysis will be done in accordance with the approved sampling plan, as stipulated in Section 3.2 of the RAP. A survey to determine the horizontal position of each well and vertical elevation of the measuring points will be conducted before water level measurements are made.

Remedial Investigation Report

Within 90 days of completing the second monitoring round described above, a report summarizing the results of the Remedial Investigation will be prepared follows:

SECTION B

Y.V

}

QUALITY ASSURANCE PROJECT PLAN

LUDIE OF COMECHES

mi BO

	Monttoring Mall Conattueston and Includistion	
ybbs	MDIA BET SOT No. 7,20	
o°a	Audits and comeuctabl action	6
d.O	MUNICIPO VANDASIS VAD BREU DESTED	2
	3, 9 Docum at Control and Revosaliscolug	ช
	1.2 Subcontinter Inality Control	S
	3.1 Fealalag	3
9 . o	oder - reced between	3
2.0	PROJECT OCCUPATION AND RESPONSIBILITIES	2
	1.2 Qualicy objectives	5 -
	til Backé jourd	٤
F° C	SECTION CAPEAGO	

(11.15-30)25-000

Õ

Page: 1 of 6

Date: November 1986 Number: QAE317-600

Revision: 0

1.0 INTRODUCTION

1.1 Background

ERT and the City of St. Louis Park will complete certain tasks in fulfillment of the Consent Decree and Remedial Action Plan for the St. Louis Park Site. This Quality Assurance Plan pertains to all work to be performed by ERT and other contractors to install six new groundwater monitoring wells in the Drift-Platteville Aquifer. Further details on the work to be performed, its purpose and the methodology to be employed may be found in the Site Management Plan.

1.2 Quality Objectives

The purpose of this Quality Assurance, Plan is to define the Quality Assurance and Quality Control provisions to be implemented to ensure that:

- The new monitoring wells will conform to design and location specifications given in the Site Management Plan.
- The work is performed in an efficient manner.
- Field records generated during the course of the field work are complete and accurate.

Ď

Page: 2 of 6

Date: November 1986 Number: QAE317-600

Revision: O

2.0 PROJECT ORGANIZATION AND RESPONSIBILITIES

The project organization is illustrated in Figure 2-1. The Project Manager, Mr. William Gregg will oversee and coordinate all project activities, schedule and direct all field activities and will conduct correspondence with St. Louis Park. The Project Manager/Field Coordinator is also responsible for maintaining records of the work performed on the project and for archiving those records in the Central File upon completion of the work. The Project Quality Assurance Officer is responsible for ensuring that this plan is implemented and that project data undergo technical and peer review, as necessary. The drilling and well installation contractor will perform all work necessary to install the new monitoring wells.

3.0 QA/QC - FIELD ACTIVITIES

3.1 Training

All field personnel working on the Drift-Platteville Aquifer Northern Area Remedial Investigation (including subcontractors) will receive training on the purpose of the work, the procedures to be employed and the Project Health and Safety Plan.

3.2 Subcontractor Quality Control

Subcontractor quality control is that system of activities which ensures that products or services obtained from subcontractors fulfill the needs of the project.

Page: 3 of 6

Date: November 1986 Number: QAE317-600

Revision: 0




Figure 1-1 Project Quality Assurance Organization

Page: 4 of 6

Date: November 1986 Number: QAE317-600

Revision: 0

Periodic quality control inspections of each contractor will be performed by the ERT Project Manager/Field Coordinator to evaluate adherence to the project QA Plan and the project Health and Safety Plan. Inspection will include (as appropriate):

- o Type and condition of equipment,
- o Calibration procedures,
- o . Personnel qualifications,
- o Decontamination procedures,
- o Documentation.

Results of the inspection will be entered in the field notebook.

3.3 Document Control and Recordkeeping

Document Control for the remedial investigation serves a two-fold purpose. It is a formal system of activities that ensures that:

- 1) All participants in the project are promptly informed of revisions of the Quality Assurance Plan; and
- 2) All critical documents generated during the course of the work are accounted for during, and at the end of the project.

This QA Plan and all Standard Operating Procedure documents have the following information on each page:

Page: 5 of 6

Date: November 1986

Number: QAE317-600

Revision: 0

o Document Number

- o Page Number
- o Total number of pages in document
- o Revision number
- o Revision date

When any of these documents are revised, the affected pages are reissued to all personnel listed as document holders with updated revision numbers and dates. Issuance of revisions is accompanied by explicit instructions as to which documents or portions of documents have become obsolete.

Control of, and accounting for documents generated during the course of the project is achieved by assigning the responsibility for document issuance and archiving. For the Drift-Platteville Aquifer Northern Area Remedial Investigation, the ERT Project Manager/Field Coordinator has this responsibility.

Documentation for the project will either be recorded in non-erasable ink, or will be photocopied promptly upon completion, and the photocopies dated. All documents will be signed by the person completing them.

4.0 NUMERICAL ANALYSIS AND PEER REVIEW

All numerical analyses, including manual calculations, mapping, and computer modeling will be documented and

And the state of t

Page: 6 of 6

Date: November 1986

Number: QAE317-600

Revision: 0

subjected to quality control review in accordance with ERT SOP 2005. Numerical Analysis and Peer Review. All records of numerical analyses will be legible.

reproduction-quality and complete enough to permit logical reconstruction by a qualified individual other than the originator.

5.0 AUDITS AND CORRECTIVE ACTION

ERT conducts periodic audits to assess the level of adherence to QA policies, procedures and plans.


Whenever quality deficiencies are observed that warrant immediate attention, formal corrective action request forms are issued to the project manager by the Quality Assurance Department. The QA Department retains one copy of the form when it is issued. The project manager completes the form and signs it when corrective action has been implemented, and returns the original to the QA Officer to close the loop.

The Quality Assurance Department maintains a record of all corrective action requests and reports their status to ERT management in a quarterly report.

Should an audit be conducted on the Drift-Platteville Aquifer Northern Area Remedial Investigation work, St. Louis Park will be apprised of the audit findings and of any corrective action that is requested and performed.

APPENDIX

ERT SOP No. 7220 MONITORING WELL CONSTRUCTION AND INSTALLATION



Organizational Acceptance Originator Department Manager Divisional Manager Group Quality Assurance Officer Other		Manager Cettur & Tyrum anager Toman Manager	
Revisions	Changes	Authorization	Date
1	Update	5/:1/	3 197
	•	CEN	3 2 34
		S CEN ACL	3/2/24
		Em	3-2-84

STANDARD OPERATING PROCEDURE

Title: Monitoring-Well Construction and Installation bi 1st Otr 198.

Date: Number: 7220

Revision:

Page

1.0 Purpose and Applicability

This SOP establishes the method for installing observation standpipes. or monitoring wells. These wells will be installed to: determine the depth to ground water, monitor ground-water fluctuations and obtain samples of ground water for laboratory testing.

2.0 Responsibilities

It is the responsibility of the project geologist/engineer to directly supervise the construction and installation of each monitoring well by the contract driller to ensure that the well-installation specifications are adhered to and to record all pertinent data on the approved forms.

3.0 Supporting Materials

The monitoring well shall consist of a commercially available well screen constructed of brass, stainless steel or slotted PVC plastic pipe of minimum 2-inch nominal ID (inside diameter). The length of the screened area and the gage of the screen or slots shall be determined by the inspecting geologist depending upon the grain-size distribution of the soils. Blank plastic, black, galvanized or stainless steel pipe of minimum 2-inch ID shall be used to complete the standpipe approximately 2 feet above the existing grade. The riser pipe shall be connected by flush, threaded joints. No solvent or anti-sieze compound shall be used on the joints.

The section of riser pipe that sticks up above ground shall be protected by 3 or 4-inch diameter steel guard pipe, up to 5 feet long set 2 feet into the concrete surface seal. The top of the guard pipe shall have a vented lockable cap.

Other materials used for well construction include silica sand, bentonite, cement, and a calibrated tape for length measurements and water-level measurements. Construction materials are generally provided by the drilling subcontractor.

4.0 Procedure for Construction

- 4.1 After drilling and soil sampling has been completed, the casing shall be flushed free of cuttings to develop a clean, uniform hole. Flushing shall be continued until the return water is clear.
- 4.2 Grouting of the borehole to the well-screen tip elevation shall be required if the tip is to be above the bottom of the borehole. A heavy plumb bob on a calibrated tape shall be used to determine the depth of the boring and the depth to the top of the grout plug.

STANDARD OPERATING PROCEDURE

Page ot

Date:

Revision:

1st Otr 198. 7220

Number:

Title:

Monitoring-Well Construction and Installation

- 4.3 The well screen and riser pipe shall then be assembled. The assembled screen and riser or its constituent parts shall be decontaminated as described in SOP 7600, Decontamination.
- 4.4 The rise and screen shall be carefully placed in the borehole to ensure that it is centered in the hole.
- 4.5 The annular space surrounding the screened section of the monitoring well and at least two feet above the top of the screen shall be filled with clean, medium to coarse sand.
- 4.6 After the sand filter has been emplaced, the monitoring well shall be filled approximately 2 to 3 feet above the existing water table with clear water and the drop in water level observed to ensure that the monitoring well is functioning. If the water level does not drop at a rate consistent with the soil type at the tip, the monitoring well shall be removed and the borehole washed before the monitoring well is reinstalled.
- 4.7 It may be necessary to seal off the well screen by placing a grout seal on top of the sand at a specified depth. The project geologist/engineer, or shall give detailed instructions if sealing off of the well screen is required. This grouting may consist of a bentonite seal of approximately 3 feet in thickness to prevent vertical flow within the boring from affecting the screened area.
- 4.8 The remaining length of borehole shall be backfilled with sand or grout to within 2 feet of the ground surface. This grouting may consist of a bentonite/cement mixture made to required specification.
- 4.9 The 3- or 4-inch diameter steel guard-pipe shall be placed around the riser, and the borehole around the guard pipe shall be dug out to approximately a 1-foot radius to a depth of 2 feet, and filled with concrete. All completed wells will have identification numbers clearly painted on the cap and guard pipe with bright colored paint.

5.0 Documentation Procedures

5.1 During installation of each monitoring well a series of measurements shall be taken and documented. These measurements shall include:

length of screen

length of riser pipe

total length of well

depth to stabilized water level

STANDARD OPERATING PROCEDURE

Page

Date:

1st Qtr 198.

Number: Revision:

7220

Title:

Monitoring-Well Construction and Installation

Other data include type and length of casing, diameters of the respective components, thicknesses and different types of grouting materials, and elevation of the top of the guard pipe and ground surface after surveying is complete.

5.2 All data shall be recorded on site onto the ground-water monitoring well installation report and all wells shall be referenced onto the appropriate site map. A field book and/or boring log can be used as other means of recording data. All documentation shall remain in the project files indefinitely.

JECT	SITE DATE: START	FINISH
ATION	GROUND ELEV.	TOTAL DEPTH (FT.)
TRACTOR	LOGGED BY	СНК'О ВҮ
SURVEY DATUM GROUND BENTONITE CEMENT CEMENT O DOT	GROUND SURFACE OWAY BOX ELEVATION OR STITE GROUND SURFACE THICKNESS OF SURFACE INDICATE ALL SEAR THICKNESS AND TY ELEVATION/DEPTH CASING INSIDE DIAMETER OF CASING INSIDE DIAMETER OF CASING TYPE OF BACKFILL DIAMETER OF BOR SCREEN GAUGE OR TYPE OF BACKFILL TYPE OF BACKFILL ELEVATION/DEPTH CONTROL TYPE OF BACKFILL TYPE OF BACKFILL ELEVATION/DEPTH CONTROL TYPE OF BACKFILL ELEVATION/DEPTH ELEVATION/DEPTH	FACE SEAL SEAL LS SHOWING DEPTH, PE OF CASING OF RISER PIPE L AROUND RISER EHOLE M OF BOTTOM OF RISER SIZE OF OPENINGS L POINT

Health i

SAFETY PLAN

for the

St. Louis Park Site Drift Platteville Aquifer Northern Area Remedial Investigation (Name of Site/Facility)

Located in

	St. Louis Park, (City)	Minnesota (State)
,	Project Number:	E317-600
	Date:	November 3, 1986
	-	
Prepared	By: Kevin Powers	Approved By: William M Hesq Project Manager
		Project Manager Date: 10/30/86
Date:	11/3/86	
		Health & Safety Manager
		Date:

SITE DESCRIPTION

WORK SITE DESCRIPTION:

Monitoring well installation work is to be performed in various
public, commercial and residential areas within the city of St. Louis
Park.
COMPOUNDS OF CONCERN: Coal tar and creosote. Species present may include phenols and Polynuclear Aromatic Hydrocarbons including, e.g.
Benzo (a) Pyrene, Benz (a) Anthracene or Quinoline. These compounds
are expected to be present at very low concentrations and not to pose
any direct exposure hazard to the work team.
PHYSICAL STATE OF COMPOUNDS: Disolved or suspended in ground water in trace quantities.

SCOPE OF WORK

ERSONNE	L REQUIREMENTS:	
	NAME	RESPONSIBILITY
	Bill Gregg	Coordinate Well Installation
	Subcontractor	Perform Well Installation
	· · · · · · · · · · · · · · · · · · ·	
	•	
PATNING	PROUTERMENTS. Pasnirator	training and respirator fit test
	Cold weather	
	•	•
		· · · · · · · · · · · · · · · · · · ·
nstalla		
nstalla	ation at six locations in the	e general vicinity of the site.
nstalla	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.
nstalla no acti	ation at six locations in the	e general vicinity of the site.


HAZARD EVALUATION

OVER	ALL	HAZA	RD:		· <u>x</u> 1	LOW		<u> </u>	DIUM	_	HIGH			
								-						
•	• •						•							
•		•	•											
	•				•						``		,	
		·											•	
with	the	ope	ratio	on of	a dr	illin	ig ri	g. —	conta	1/2	o i subsa	L		
is pe	er fo	rmed	dur	ing v	inter	mont	hs.	Also	, phy	sical	hazards	ass	ociat	ed
OPER#	TIO	NAL _	HAZA	RDS:_	Pote	ntial	for	extr	<u>emely</u>	cold	weather	, if	work	-

١

PERSONAL PROTECTION REQUIREMENTS

	SPECIFICATIONS: MSA Comfo II with Type GMC-H cartridges
1	MODIFICATIONS: Respiratory protection required if odors or dust
	e objectionable in the vicinity of borings or if VOC's are
	ted in the breathing zone by an HNU reading of 10 units or
	er. · · · ·
OTE	CTIVE CLOTHING REQUIREMENT:
x	WORK CLOTHES/COVERALLS (long sleeved)
	CHEMICAL PROTECTIVE CLOTHING. TYPE? -
	CHARTONE PROTECTIVE CONTINUE. TIPE:
	WORK SHOES (STEEL TOE/SHANK)
×	BOOTS. TYPE? Slush type
X	GLOVES. TYPE? Nitrile - for handling tools and equipment
	obovib. IIIb. Nicilie tor handling cools and equipment
x	HARD HAT
<u></u>	FACE SHIELD
х	SAFETY GLASSES/GOGGLES
	DAFETT GEREGEE/ GOGGEE
	MODIFICATIONS. Hard bat/safety alacase required within 25
· • •	MODIFICATIONS: Hard hat/safety glasses required within 25
00	radius of operating drill rig.
``	ORING PROUTERWING
	ORING REQUIREMENTS:
l	INSTRUMENT: HNU PI-101
	MONITORING PROCEDURE: Monitor breathing zone in accordance with
	manufacturer's instructions during soil boring operations
	INSTRUMENT:
	MONITORING PROCEDURE



DECONTAMINATION PROCEDURES

ECONTAM	NATION PROCEDURE(S):
1)	ITEM(S): Gloves, boots and other equipment as necessary
	PROCEDURE: Wash with alconox detergent and rinse with
	clean water
2)	ITEM(S):
	PROCEDURE:
ISPOSAL	PROCEDURE: General refuse for all consumables.
	PROCEDURE: General refuse for all consumables.
·	
·	
PECIAL 1	INSTRUCTIONS:
PECIAL :	

EMERGENCY REFERENCE

AMBU	LANCE: 93	11			
	-				
POLI	CE: 9	11	· · · · · · · · · · · · · · · · · · ·		
FIRE	: · · · · 9:	11		•	
HOSP	PITAL: Me	thodist Hospita	ı		
		5500 Excelsion			
			Minnesota		
		932-5000			
					-
		TO HOSPITAL:			
So			to Methodist Hos		
	· · ·				· · · · · · · · · · · · · · · · · · ·
				· · ·	· · · · · · · · · · · · · · · · · · ·
					·
DO 1 0	ON CONTRO		23.43		`
POIS	ON CONTRO	L CENTER: 347-	3141	•	
NATT	ONAT. RESP	ONSE CENTER: 1	- 800-424-8802		
0	CORPORAT	E:			
		NON	I-RESPO	DNSI	VE.
			MPCA Douglas J.	Robohm	612-296-7395
0	AGENCY R	EPRESENTATIVE:	EPA Daniel J. E	Bickhell	312-886-7341.
0	CLIENT R	e presentati ve :	MONI D	$CCD \cap$	NICIVE

NEAREST PHONE: Public phones in St. Louis Park

SECTION D COMMUNITY RELATIONS PLAN

COMMUNITY RELATIONS PLAN

The Drift-Platteville Aquifer - Northern Area Remedial Investigation is to be completed in conjunction with the enactment of various other work tasks embodied in a proposed Consent Decree - Remedial Action Plan for Reilly Tar, Minnesota, N.P.L. Site. All community relations programs related to the enactment of the Consent Decree tasks shall be coordinated through the following agencies:

United States Ms. Judy Beck

United States Environmental Protection Agency

(312) 353-1325

State of Minnesota Ms. Susan Brustman

Minnesota Pollution Control Agency

(612) 296-7769

City of St. Louis Park Ms. Sharon Klumpp

City of St. Louis Park

(612) 924-2523

